

IN THE EVENT OF A CHÉMICAL EMERGENCY INVOLVING A SPILL, LEAK, FIRE, EXPOSURE OR ACCIDENT CONTACT THE BELOW

EMERGENCY 24 HOUR NUMBER GE

GENERAL INFORMATION NUMBER

Material Safety Data Sheet

CHEMTREC 1-800-424-9300

MAPEI 1-954-246-8888

CPSC STATEMENT
CAUTION - PC

POTENTIAL SKIN AND EYE IRRITANT TO SENSITIVE INDIVIDUALS. HARMFUL OR FATAL IF SWALLOWED.

Not Regulated

DOT HAZARD CLASSIFICATION

IDENTITY (As shown on label):

Ultraprime L

Copolymer acrylic concentrated primer for self-leveler and repair compounds.

SECTION I - GENERAL INFORMATION

MANUFACTURER:

MAPEI CORPORATION

1144 East Newport Center Drive Deerfield Beach, FL 33442

PREPARED BY:

Donald House

Manager of Product and Employee

PRINT DATE:

Monday, July 15, 2002

SECTION II - PHYSICAL CHARACTERISTICS

Maximum VOC
Boiling Point
Vapor Pressure (mmHg)
Vapor Density (AIR=1)
Specific Gravity (H20=1)
M/E
Melting Point (F)
N/E
N/E

Evaporation Rate (Butvl Same as water.

Acetate=1)

Solubility in water

Appearance and Odor

Miscible

White milky liquid. Latex odor.

VOC calculated per (Rule 1168, South Coast Air Quality District - California)

SECTION III - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components

Other Limits

% Percent

(specific chemical identity; common names):

OSHA (PEL)

ACGIH (TLV-TWA)

Recommended

(Optional)

THIS PRODUCT CONTAINS NO HAZARDOUS INGREDIENTS AS DEFINED BY THE OSHA HAZARD COMMUNICATION STANDARD - 29 CFR 1910.1200.

FOR CALIFORNIA: THIS PRODUCT CONTAINS NO CHEMICALS REPORTABLE UNDER PROPOSITION 65.

HMIS (Hazardous Materials Identification System) Rating: Health - 1 Fire - 0 Reactivity - 0 Protection - B

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flash Point (F) - >212°F

Lower Explosive Limit (%) - N/E

Upper Explosive Limit (%) - N/E

Extinguishing Media

Product will not burn until all water content has evaporated. Water spray, carbon dioxide, dry chemical or foam.

Special Fire Fighting Procedures

Wear standard fire fighting gear with self-contained breathing apparatus.

Unusual Fire and Explosion Hazards

Some decomposition products may be harmful.

SECTION V - REACTIVITY DATA

STABILITY: Stable

Conditions to Avoid None known. incompatibility (Materials to Avoid)

Strong oxidizing agents, strong acids, and strong bases.

Hazard Decomposition of By-products

Carbon monoxide, carbon dioxide, oxides of nitrogen, and

other unidentified organic compounds.

POLYMERIZATION: Will Not Occur

Conditions to Avoid

None known.

SECTION VI - MEALTH HAZARD DATA

ROUTES OF ENTRY:

Inhalation? YES

Skin? YES

Ingestion? YES

N/A = Not Applicable.

N/E = Not Established.

Ultraprime L MSDS Page 1 of 2

HEALTH HAZARDS (ACUTE AND CHRONIC)

Acute: Inhalation or contact can cause irritation to eyes, skin, nose or throat to sensitive people. If ingested can cause

nausea, vomiting, griping, and diarrhea.

Chronic: See Section III of MSDS.

CARCINOGENICITY: NTP - NO IARC - NO OSHA - NO

Signs and Symptoms of Overexposure

Nausea; vomiting; nose and throat irritation; eye Irritation; and skin irritation.

Medical Conditions That Can Be Aggravated by Exposure

Allergies, skin and respiratory disorders. Product sensitivity.

EMERGENCY AND FIRST AID PROCEDURES

Eyes - Flush with cool water for 15 minutes while holding eyelid open. If imitation persists, seek medical attention

mmediately.

Skin - Avoid contact with skin. Remove contaminated clothing. Wash affected area thoroughly with soap and

water. If irritation persists, seek immediate medical attention.

Inhalation - Remove to fresh air. If not breathing, trained personnel should Initiate artificial respirations and immediate

medical attention should be obtained.

Ingestion - Do not induce vomiting. Do not give anything by mouth to an unconscious person. Seek medical attention

immediately.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken if Material is Leaked or Spilled

White using appropriate protective equipment, place spilled material in poly drum, or container requirement by local disposal company, and store in a safe place till material can be disposed of in accordance with regulations.

Waste Disposal Method

Dispose of in accordance with local, state, and federal regulations governing your location.

Precautions to be taken during Handling and Storage

Keep container closed when not in use. Store at 60-95°F and out of the sun. Use adequate ventilation to avoid breathing vapors when cover is removed.

Other Precautions

Avoid prolonged skin contact.

SECTION VIII - CONTROL MEASURES

Respiratory Protection: If workplace exposure limit of product is exceeded, a NIOSH/MSHA approved air supplied respirator

Is required in absence of proper environmental control. Engineering or administrative controls

should be implemented to reduce exposure.

VENTILATION: Local Exhaust Special

Use in WELL VENTILATED areas only.

N/A

Mechanical Other

Use only intrinsically safe devices.

Eve Protection - Safety glasses or goggles as necessary to Protective Gloves - Impervious. (Nitrile, rubber, or better)

prevent eye contact.

Other Protective Equipment - As needed to minimize contact with skin.

WORK AND HYGIENE PRACTICE

Remove contaminated clothing immediately. Wash hands, after each use and before eating, drinking, or using toiletries. Minimize contact of product on skins.

The Information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from the use thereof. MAPEI Corporation assumes no responsibility for personal injury or property damage to vendes, users, or third parties caused by the material.

Such vendees or users assume all risks associated with the use of the material.

Ultraprime L MSDS Page 2 of 2